

Under Review Notification

Raised By: VANESSA MOREL

Product #: DART TOOLING BELL

Date: 17.10.23

Product Name: DEHYDRATOR TAIL ROTOR

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
RB T102103-3	RB T102103 REV 1	Y	Y	N	Y	Y	Y	N	17-709	Use prelim new drawing or scrap
RB T102103-5	RB T102103 REV 1	Y	Y	N	Y	Y	Y	N	17-709	Use prelim new drawing or scrap
RB T102103-7	RB T102103 REV 1	Y	Y	N	Y	N	Y	N	17-709	Use prelim new drawing or scrap

Description of Issue: FIT ISSUE

RB T102103-3 REV PC: WAS .066/.061 IS .064 +/- .005",
 RB T102103-5 REV PC: WAS .066/.061 IS .064 +/- .005", COCENTRICITY GD&D TOLERANCE REMOVED
 RB T102103-7 REV PC: WAS .050 x 2-1/2 BECOME McMaster#6517K27

Distribution:

VP Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
Director of Operations	Engineering Project Managers	Production Planners	
Director Quality Assurance	Engineering Clerk	Purchasing Manager	
Director of Engineering	Customer Support Manager	Technical Support	